



Contents

91 - Radio, telephone, navigation system	1
1 Communication Systems	1
1.1 Locating defects and indicating faults	1
2 CD Player R89	2
2.1 CD Player R89 „GAMA“ ► 12/07 and/or „RCD 300“ 08/05 ►	2
2.2 "CD player" R89 „Clarion MP3“ - 07/05 ►	9
2.3 "CD player" R89 „RCD 200“ (Europe)	13
2.4 "CD player" R89 „1 Din Clarion with USB “ - 09/07 ►	20
2.5 "CD player" R89 „1 Din MID“ - 01/08 ►	25
2.6 "CD player" R89 - „Concept“ - 03/08 ►	29
3 Loud speakers	34
3.1 Left front bass speaker R21 ; Right front bass speaker R23 and/or Left rear bass speaker R15 ; Right rear bass speaker R17 - replace	34
3.2 Left front treble speaker R20 and/or Right front treble speaker R22 (front tweeter) - replace	34
4 Multifunction steering wheel	36
4.1 Command keys - remove and install	37
4.2 Multifunction steering wheel - adjust	37
5 Antenna system	38
5.1 Windscreen antenna R31 and/or Antenna amplifier R24 (► 04/07)	38
5.2 Antenna R11 (►12/07)	39
5.3 Antenna R11 (01/08 ►) - except Europe vehicles	40
5.4 Antenna R11 - remove and install	41
5.5 Antenna cable (Fox) - general overview of assembly	42
5.6 Antenna cable (Fox) - remove and install	43
6 Observations pertaining to the operation of telephones and radio communication devices (Europe vehicles)	45
6.1 General notes	45
6.2 Instructions pertaining to assembly work.	46
6.3 Radio communication device - general overview	47
6.4 Emissions powers and locations of installation of the antennas	48
7 Interference suppression measures	49